



**Forane® 134a**

**Pressure-Temperature Chart**

Saturation  
Temperature    Pressure  
[°F]            [psig]

-50	18.7
-45	16.9
-40	14.8
-35	12.5
-30	9.8
-25	6.9
-20	3.7
-15	0.1
-10	1.9
-5	4.1
0	6.5
5	9.1
10	11.9
15	15.0
20	18.4
25	22.1
30	26.0
35	30.3
40	35.0
45	40.0
50	45.4
55	51.1
60	57.3
65	63.9
70	71.0
75	78.6
80	86.6
85	95.1
90	104.2
95	113.8
100	124.1
105	134.9
110	146.3
115	158.4
120	171.1
125	184.5
130	198.7
135	213.6
140	229.3
145	245.7
150	263.0

Red numerals = inches Hg below 1 atm