



**Forane® 404A**

**Pressure-Temperature Chart**

Saturation Temperature [°F]	Liquid Pressure [psig]
-50	0.6
-45	2.7
-40	5.0
-35	7.6
-30	10.4
-25	13.4
-20	16.8
-15	20.5
-10	24.5
-5	28.8
0	33.5
5	38.6
10	44.0
15	49.9
20	56.2
25	63.0
30	70.3
35	78.1
40	86.4
45	95.2
50	104.7
55	114.7
60	125.3
65	136.6
70	148.6
75	161.2
80	174.6
85	188.8
90	203.7
95	219.4
100	235.9
105	253.4
110	271.7
115	290.9
120	311.1
125	332.3
130	354.5
135	377.8
140	402.2
145	427.7
150	454.4